Word Count: 2565

## Plagiarism Percentage 2%

## sources:

1% match (Internet from 28-Nov-2014)
http://onlinepubs.trb.org/onlinepubs/nchrp/nchrp\_syn\_440.pdf

1% match (Internet from 14-Sep-2010)

http://mmrs.fema.gov/library/file;?type=publishedFile&file=fema389\_ch4.pdf&fileid=1137a560-65bf-11db-8645-000bdba87d5b

## paper text:

Civil Engineering Dimension, Vol. 20, No. 1, March 2018, 35-40 DOI: 10.9744/CED.20.1.35-40 ISSN 1410-9530 print / ISSN 1979-570X online Performance of an Existing Reinforced Concrete Building Designed in Accordance to Older Indonesian Seismic Code: A Case Study for a Hotel in Kupang, Indonesia Pudjisuryadi, P.1\*, Lumantarna, B.1, Setiawan, R.1, and Handoko, C.1 Abstract: The recent seismic code SNI 1726-2012 is significantly different compared to the older code SNI 1726-2002. The seismic hazard map was significantly changed and the level of maximum considered earthquake was significantly increased. Therefore, buildings designed according to outdated code may not resist the higher demand required by newer code. In this study, seismic performance of Hotel X in Kupang, Indonesia which was designed based on SNI- 1726-2002 is investigated. The structure was analyzed using Nonlinear Time History Analysis. The seismic load used was a spectrum consistent ground acceleration generated from El-Centro 18 May 1940 North-South component in accordance to SNI 1726-2012. The results show that Hotel X can resist maximum considered earthquake required by SNI 1726-2012. The maximum drift ratio is 0.81% which is lower than the limit set by FEMA 356-2000 (2%). Plastic hinge damage level is also lower than the allowance in ACMC 2001. Keywords: Indonesian seismic code; non-linear time history analysis; reinforced concrete; seismic performance. Introduction Earthquake is one of many loads that should be considered in designing a building. Seismic resistant buildings are designed against earthquake load based on seismic code which is periodically updated. The last update for Indonesian seismic code was from SNI1726-2002 to SNI 1726-2012 and the seismic hazard map is changed considerably. Besides the change of the seismic hazard map, SNI 1726- 2012 also increases the maximum considered earthquake (MCE) level from 500 to 2500 year return period [1,2]. Peak bedrock acceleration map with 500 year return period in SNI1726-2002 is shown in Figure 1. While Figure 2 shows peak ground acceleration map with 2500 return period in SNI 1726-2012. One example of this change is presented in Figure 3, for Kupang city in Indonesia (very dense soil). In Figure 3 the elastic design response spectra in SNI 1726-2012 which is 2/3 of the response spectra of the MCE is compared to elastic design response spectra in SNI1726-2002. 1 Civil Engineering Department, Faculty of Civil Engineering and Planning, Petra Christian University, Jl. Siwalankerto 121-131, Surabaya 60236, INDONESIA \* Corresponding author: pamuda@petra.ac.id Note: Discussion is expected before June, 1st 2018, and will be published in the "Civil Engineering Dimension", volume 20, number 2, September 2018. Received 12 February 2018; revised 12 March 2018; accepted 20

March 2018. Figure 1. Peak Bedrock Acceleration Map with 500 Year Return Period in SNI1726-2002 Figure 2. Peak Ground Acceleration Map with 2500 Year Return Period in SNI 1726-2012 The change of the elastic design response spectrum is not significant in this case. However SNI 1726- 2012 introduces different seismic reduction factor. For dual systems structure (reinforced concrete special moment frames and shear walls), the seismic reduction factor in SNI1726-2002 is 8.5. While in SNI 1726-2012, the response modification coefficient is 7. The resulting nominal earthquake loads (elastic design response spectrum divided by the seismic reduction factor) will differ more significantly. With lower nominal earthquake required in older seismic code, and higher maximum considered earthquake specified by the newer code, building performances designed with the older code are imperative to be investigated. Figure 3. Comparison of Acceleration Response Spectra Between SNI1726-2002 and SNI 1726-2012 in Kupang City – Indonesia (very dense soil) Considered Building In this study, a six story Hotel X in Kupang, Indonesia with very dense soil site classification is chosen to be investigated. Besides the use of the older seismic code (SNI 1726-2002), the hotel was also designed based on older structural concrete code (SNI03-2847-2002). Indonesian structural concrete code was last updated from SNI03-2847-2002 to SNI 2847:2013 [3,4]. However, there were no significant changes in those structural concrete codes. The elevation and plan views of Hotel X are shown in Figure 4 and Figure 5, respectively. The shearwall positions are marked in Figure 5. (a) (b) Figure 4. Elevation View of Hotel X: a) Longitudinal section; b) Transverse section Figure 5. Typical Plan View of Hotel X (shown on the 3rd floor) Analysis Hotel X structure was first modeled in SAP2000 software [5]. Because of some limitations on SAP2000, every Lshaped shear wall in the structure was modeled as two rectangular column elements which were connected using diaphragm joint con- straint. The frame non-linear hinge properties (moment-curvature and forcedisplacement relation- ships) were generated using CUMBIA software [6]. The structure was then analyzed using Nonlinear Time History Direct Integration Analysis. The seismic load used was a spectrum consistent ground acceleration generated from El Centro 18 May 1940 North-South component in accordance to elastic design earthquake level (2/3 of MCE) and MCE of Kupang City based on SNI 1726-2012. The earthquake loads were applied on the structure twice as 1- directional earthquake in X (longitudinal) and Y (transverse) directions. Building Seismic Performance Seismic performance of the structure was determined based on maximum drift ratio and plastic hinge damage level. Table 1 shows earthquake performance matrix and drift ratio limits for every performance level based on FEMA 356-2000 [7]. While damage index limits for every performance level based on ACMC 2001 is shown on Table 2 [8]. With the assumption that 2/3 of MCE is comparable to earthquake with 500 year return period (10% probability of exceedance in 50 years), according to FEMA 356-2000, the target performance levels for basic objective are "k" and "p" in Table 1 (Life Safety Performance Level for elastic design earthquake, and Collapse Prevention Performance Level for MCE). While according to ACMC 2001, target performance levels for elastic design earthquake Pamuda P. et al./ Performance of an Existing Reinforced Concrete Building / CED, Vol. 20, No. 1, March 2018, pp. 35–40 Table 1. Earthquake performance matrix based on FEMA 356-2000 Target building performance level Operational Immediate occupancy Life safety Collapse prevention performance level (1-

performance level (1-B) performance level (3- performance level (5-E) A)

C) Earthquake hazard level

2

Drift ratio - < 0.5% 0.5% - 1% 1% - 2% Table 2. Damage index limits based on ACMC 2001 Seismic performance level Operational performance Damage control limit level Serviceability limit state state Safety Earthqu Minor-to-moderate ake level earthquake? Severe earthquake? Ultimate earthquake? Damage index < 0,1 ? ? ? 0,1 - 0,25 X X ? ? 0,25 - 0,4 X ? 0,4 - 1 level and MCE (comparable to severe earthquake and ultimate earthquake) are Damage Control and Safety Limit State, respectively. From the analysis results, story displacements, drift ratios, and member plastic hinge damage levels were recorded. Table 3 summarizes the story displace- ments and drift ratios of the structure in both directions due to elastic design and maximum con- sidered earthquake levels. The same story dis- placements and drift ratios are also illustrated in Figure 6 and Figure 7, respectively. Moreover, the performance level limits according to FEMA 356- 2000 are also plotted in Figure 7. From Figure 7, it can be seen that the seismic performance of Hotel X according to FEMA 356-2000 is very good. Even when the Hotel X was subjected to MCE, the drift ratio still showed Life Safety Performance level in both directions. Figure 6. Hotel X Displacement Graph Seismic performance of Hotel X was also determined based on the worst plastic hinge damage level due to the earthquake loads, with damage index limits set by ACMC 2001. Typical frame plastic hinge damages of the structure are shown in Figures 8 to 15. In those figures, centerline of the shear walls are marked with dotted line boxes, while the beams between the center line of the shear walls to the nearest plastic hinges are in fact rigid beams to simulate the width of the walls. Figures 8 to 11 show the frame damages due to design earthquake and MCE in x-direction, while Figures 12 to 15 show the frame plastic hinge damages in y-direction. Plastic hinge damage marks used in the figures are listed in Table 4, which correspond to the performance levels set by ACMC 2001 (Table 2). Figure 7. Drift Ratios of Hotel X due to Design and Maximum Considered Earthquake Compared to FEMA 356-2000 limits Seismic performance of Hotel X was also determined based on the worst plastic hinge damage level due to the earthquake loads, with damage index limits set by ACMC 2001. Typical frame plastic hinge damages of the structure are shown in Figures 8 to 15. In those figures, centerline of the shear walls are Table 3. Hotel X displacement and drift ratio Hotel X displacement (mm) Story Elastic design earthquake Maximum considered level earthquake X-dir. Y-dir. X-dir. Y-dir. Roof 75,53 106,59 134,76 136,84 5 67,61 96,28 124,47 127,41 4 59,46 82,19 109,19 112,77 3 48,26 64,72 86,86 92,66 2 36,52 47,82 63,91 70,41 1 18,22 26,09 30,79 38,58 marked with dotted line boxes, while the beams between the center line of the shear walls to the nearest plastic hinges are in fact rigid beams to simulate the width of the walls. Figures 8 to 11 show the frame damages due to design earthquake and MCE in x-direction, while Figures 12 to 15 show the frame plastic hinge damages in y-direction. Plastic hinge damage marks used in the figures are listed in Table 4, which correspond to the performance levels set by ACMC 2001 (Table 2). Table 4. Plastic hinge markers Plastic hinge marker Plastic hinge damage level Operational performance level Serviceability limit state Damage control limit state Safety limit state Figure 8. Frame 1 Plastic Hinges due to Design Earthquake in x-direction Figure 9. Frame 6 Plastic Hinges due to Design Earth- quake in x-direction From Figures 8 and 9, it can be seen that the worst plastic hinge damage level due to design earthquake in xdirection is serviceability limit state, which is on Hotel X drift ratio (%) Elastic design earthquake Maximum considered level earthquake X-dir. Y-dir. X-dir. Y-dir. 0,3076 0,3338 0,3336 0,401 0,3657 0,4386 0,4778 0,5706 0,4148 0,5448 0,6977 0,7089 0,405 0,5305 0,8079 0,6813 0,4258 0,5483 0,7935 0,6992 0,351 0,5265 0,6284 0,7786 base of the right shear wall. The other plastic hinges on left shear wall, columns, and beams are on operational performance level. For elastic design earthquake, the worst plastic hinge damage level allowed in ACMC 2001 is damage control limit state. Therefore, Hotel X seismic performance due to design earthquake in x-direction is very good. Figure 10. Frame 1 Plastic Hinges due to Maximum

Considered Earthquake in x-direction Figure 11. Frame 6 Plastic Hinges due to Maximum Considered Earthquake in x-direction Figure 12. Frame D Plastic Hinges due to Design Earth- quake in y-direction Pamuda P. et al./ Performance of an Existing Reinforced Concrete Building / CED, Vol. 20, No. 1, March 2018, pp. 35–40 Figure 13. Frame I Plastic Hinges due to Design Earth- quake in y-direction Due to MCE in x-direction, the worst plastic hinge level is also serviceability limit state, which occurs on shear walls and a few beams. All plastic hinges on columns and majority of beams are on operational performance level. All plastic hinges on Hotel X due to MCE in x-direction is lower than the limit set by ACMC 2001, which is safety. The worst plastic hinge damage level due to design earthquake in y-direction is on serviceability limit state, which occurs only on shear wall. All plastic hinges on columns and beams are on operational limit state. That means all plastic hinges on Hotel X due to design earthquake in y-direction is lower than the limit set by ACMC 2001, which is damage control limit state. Figure 14. Frame D Plastic Hinges due to Maximum Considered Earthquake in y-direction Figure 15. Frame I Plastic Hinges due to Maximum Considered Earthquake in y-direction From Figures 14 and 15, it can be seen that majority of plastic hinges on Hotel X are on operational performance level. While a few plastic hinges on shear wall, columns, and beams are on serviceability limit state. As mentioned above, the worst seismic performance level allowed by ACMC 2001 due to MCE is safety. Therefore, Hotel X seismic perfor- mance level due to MCE in y-direction based on plastic hinge damage level is satisfactory. From Figures 8 to 15, it can be concluded that Hotel X seismic performance based on plastic hinge damage level according to ACMC 2001 is satisfying. Table 5 summarizes Hotel X seismic performance based on plastic hinge damage level. Table 5. Hotel X Seismic Performance according to ACMC 2001 Damage Operational Servicea- Parameter Earthquake Performance bility Limit Control Safety Level Level State Limit State Elastic Plastic Design Earthquake? Hinge Damage Level Level Maximum Considered ? Earthquake Conclusion Indonesian seismic codes for designing earthquake resistant buildings are updated periodically, arising need to evaluate buildings designed by outdated codes. In this study, a reinforced concrete structure that was design based on older seismic code (SNI 17260-2002) was evaluated according the demand of newest code (SNI 1726-2012). From the analysis, it can be concluded that the seismic performance of the structure is still satisfactory compared to allowed limits. Hotel X maximum drift ratio due to elastic design earthquake level (0.55%) and 2500 year return period earthquake (0.81%) have not exceed the limits in FEMA 356-2000 (1% and 2%). Worst plastic hinge damage level (serviceability limit state due to both earthquakes) also has not exceeded the limits in ACMC2001 (damage control limit state for elastic design earthquake level and safety level for 2500 year return period earthquake). References 1. SNI-1726-2002, Standar Perencanaan Ketahan- an Gempa untuk Struktur Bangunan Gedung, Pusat Penelitian dan Pengembangan Teknologi Permukiman, 2002, (In Indonesian). 2. SNI 1726-2012, Tata Cara Perencanaan Keta- hanan Gempa untuk Struktur Bangunan Gedung dan Non Gedung, Badan Standardisasi Nasional, 2012, (In Indonesian). 3. SNI 2847:2013, Persyaratan Beton Struktural untuk Bangunan Gedung, Badan Standardisasi Nasional, 2013, (In Indonesian). 4. RSNI-03-2847-2002, Tata Cara Perhitungan Struktur Beton untuk Bangunan Gedung, Badan Standardisasi Nasional, 2002, (In Indonesian). 5. Computers & Structures, Inc., CSI Analysis Reference Manual, Berkeley, California, USA, 2016. 6. Montejo, L.A. and Kowalsky, M.J., CUMBIA- Set of Codes for the Analysis of Reinforced Concrete Members, North Carolina State Univer- sity, Raleigh, 2007. 7. FEMA 356-2000, Pre Standard and Commentary for the Seismic Rehabilitation of Buildings, American Society of Civil Engineers, 2000. 8. ACMC 2001, Asian Concrete Model Code Level 1 & 2 Documents, International Committee on Concrete Model Code for Asia, 2001. Pamuda P. et al./ Performance of an Existing Reinforced Concrete Building / CED, Vol. 20, No. 1, March 2018, pp. 35–40 Pamuda P. et al./ Performance of an Existing Reinforced Concrete Building / CED, Vol. 20, No. 1, March 2018, pp. 35–40 Pamuda P. et al./ Performance of an Existing Reinforced Concrete Building / CED, Vol. 20, No. 1, March 2018, pp. 35–40 35 36 37 38 39 40